



DIR-615 Firmware Release Notes

DIR-615 Firmware Release Notes

Firmware: v20.22b04

Hardware: T3

Date: 2018/01/08

Note:

1. Portuguese, Spanish and English version. Default is English.
2. Support On-Page setup page.
3. Disable HT20/40 co-existence by default for DBR/DLA request

Problems Resolved:

1. Fix Repeater issue
2. Blank domain name setting in the GUI of DHCP server

Enhancements:

3. Support WISP mode, IP filter,
 4. Add time zone " GMT+4 Abu Dhabi , Muscat"
 5. Add IP filter, Mac filter function
 6. WPA2 security enhancement.
 7. Add firmware protection
-